PAGE: 1 PRINT DATE: 11/02/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 05-6J-2162 -X

SUBSYSTEM NAME: D&C - MAIN PROPULSION SYSTEM

REVISION: 1 02/22/01

PART DATA

PART NAME PART NUMBER
VENDOR NAME VENDOR NUMBER

LRU : PANEL R2 V070-730277

SRU: SWITCH, TOGGLE ME452-0102-7201

ME452-0102-8201

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

SWITCH, TOGGLE (TWO POLES, THREE POSITIONS, LEVER LOCKED) MPS PROPELLANT DUMP SEQUENCE CONTROL CIRCUIT.

REFERENCE DESIGNATORS: 32V73A2S1

QUANTITY OF LIKE ITEMS: 1

FUNCTION:

PROVIDES MANUAL "START" AND "STOP" CONTROL OF MPS PROPELLANT DUMP SEQUENCE CONTROL CIRCUIT.

PAGE 2 PRINT DATE: 11/05/01

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 05-6J-2162-02

REVISION#: 1 09/17/01

SUBSYSTEM NAME: D&C - MAIN PROPULSION SYSTEM

LRU: PANEL R2 CRITICALITY OF THIS
ITEM NAME: MPS DUMP SEQUENCE TOGGLE SWITCH FAILURE MODE: 1R2

FAILURE MODE:

CONTACT-TO-CONTACT SHORT (BOTH "START" POLES)

MISSION PHASE: LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA

103 DISCOVERY104 ATLANTIS105 ENDEAVOUR

CAUSE:

PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? YES

RTLS RETURN TO LAUNCH SITE

REDUNDANCY SCREEN A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF MANUAL "STOP" COMMAND CAPABILITY OF MPS PROPELLANT DUMP SEQUENCE CONTROL CIRCUIT.

CRITICALITY 1/1 FOR RTLS ABORTS; SWITCH FAILURE RESULTING IN INADVERTANT DUMP "START" COMMAND PREVENTS THE INITIATION OF LO2 DUMP DUE TO THE RTLS SOFTWARE READING THE DUMP SWITCH IN "START" AS A CUE FOR THE PERFORMANCE OF AN RTLS

PAGE: 3 PRINT DATE: 11/05/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 05-6J-2162-02

CONTINGENCY BAILOUT SCENARIO REQUIRING THE RETENTION OF LO2 FOR VEHICLE CG CONTROL. THE INADVERTENT FAILURE TO DUMP LO2 MAY CAUSE VIOLATION OF MAXIMUM DOWNWEIGHT FOR HEAVY MANIFESTED PAYLOADS.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT - FIRST FAILURE.

(C) MISSION:

NO EFFECT - FIRST FAILURE.

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT - FIRST FAILURE.

(E) FUNCTIONAL CRITICALITY EFFECTS:

1R/2 2 SUCCESS PATHS. TIME FRAME - POST MECO/MPS DUMP

- 1) FAILURE REQUIRING DELAY OF ET SEPARATION DELAY INTO MECO+20 SECONDS MPS DUMP TIMEFRAME.
- DUMP SWITCH FAILS IN "START" POSITION AT SAME TIME AS ET SEP INITIATION, POSSIBLY RESULTING IN INITIATION OF DUMP COINCIDING WITH MANUAL ET SEP.

RESULTS IN POSSIBLE ET/ORBITER RE-CONTACT AND POTENTIAL STRUCTURAL OR THERMAL PROTECTION SYSTEM DAMAGE. POSSIBLE LOSS OF CREW/VEHICLE.

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

(B) TEST:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

(D) FAILURE HISTORY:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

PAGE: 4 PRINT DATE: 11/05/01

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 05-6J-2162-02

(E) OPERATIONAL USE:

NO CREW ACTION CAN BE TAKEN.

- APPROVALS -

S&R ENGINEERING : W.P. MUSTY :/S/ W.P. MUSTY

S&R ENGINEERING ITM : P. A. STENGER-NGUYEN :/S/ P.A. STENGER-NGUYEN D&C ENGINEERING : LAITH COTTA :/S/ LAITH COTTA :/S/ TIM REITH :/S/ TIM REITH MPS SUBSYSTEM MGR. : TIM REITH :/S/ TIM REITH
EPD&C SUBSYSTEM MGR. : RICHARD PHAN :/S/ RICHARD PHAN
MOD : JEFF MUSLER :/S/ JEFF MUSLER
USA SAM : MIKE SNYDER :/S/ MIKE SNYDER
USA ORBITER ELEMENT : SUZANNE LITTLE :/S/ SUZANNE LITTLE
NASA SR&QA : ERICH BASS :/S/ ERICH BASS